



FIG. NOTES

- 3 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.

	<h1>HL-LED</h1> <p>SERVICE PARTS LIST</p>	Bulletin Date: <h2>Dec-17</h2>
	<p>TTI Model Number: 016 085 005</p> <p>LED HEAD LAMP</p>	<p>Starting Serial Number:</p> <p>VERSION A - K2017</p>

ITEM	PART NUMBER	PART DISCRIPTION	QTY (PCS)
1	016085001001	STRAP	1
2	016701001002	HARD HAT CLIPS (SET OF 4)	1
3	01608500501K	RATING LABEL (NOT SHOWN)	1