



FIG. NOTES

- 7 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.

	<h1>L4 HL</h1> <p>SERVICE PARTS DIAGRAM</p>	Bulletin Date: <h2>Jan-18</h2>
	<p>TTI Model Number: 016 085 005</p> <p>USB RECHARGEABLE HARD HAT HEADLAMP</p>	<p>Starting Serial Number:</p> <p>VERSION A - M2017</p>

ITEM	PART NUMBER	PART DISCRIPTION	QTY (PCS)
1	016701001004	RUBBER USB COVER	1
2	016701001003	STRAP BRACKET	1
3	016701001001	STRAP	1
4	016701001002	HARD HAT CLIP(SET OF 4)	1
5	016701002005	WALL PLUG AND MIRCO-USB CABLE (OPTIONAL)	1
6	01670100201K	RATING LABEL(NOT SHOWN)	1